

April 7, 2009,v1.0

## Processing Guides for WONDERLITE® PC-115U

- A Pre-drying 120°C x 4 hrs depending on a) Humidity
  - b) Storage conditions
  - c) Dryer's performance
- B. Barrel Setting Profile

		$\downarrow$	↓ ↓		
Grade / Application		Nozzle	Compression zone	Feeding zone	Mold Temperature *
PC-115U	max.( ° <b>C</b> )	300	310	300	70 -120
	min.( ° <b>C</b> )	250	250	230	

\* varying with

a) Thickness of molded articles

b) Cooling system design

c) Gate and runner system

## NOTE :

- 1. Keep the resin from dust and contamination during handling and production.
- 2. Do not retain the hot melt at the barrel for a long time between injection cycles.
- 3. Temperature setting of manifold system should not exceed 330°C to avoid melt from degrading.
- Purging :

Heat decomposing resins are not recommended for purging the residual WONDERLITE<sup>®</sup> and WONDERLOY<sup>®</sup> in barrel of injection machine and extruder. Polyethylene and polypropylene are the most commonly used heat stable resins for purging purpose.

For further information, please contact your local agent or fax to CHIMEI-ASAHI Technical Services Dept. at 886-6-2667983/2667984



59-1 SAN CHIA, JEN TE, TAINAN COUNTY, TAIWAN. TEL: 886-6-266-5000 FAX: 886-6-266-5555~7